December 2, 2002

# TRANSMITTAL

TO:

Gregory Olmstead, UST Section Supervisor

Department of Health, Solid & Hazardous Waste Branch

FROM:

Joel Narusawa


Environmental Compliance Officer

SUBJECT:

DAGS Project No. 11-31-4117, Mauna Kea UST Removal Closure Report

Enclosed is a copy of the closure report for a UST removal at the University of Hawaii Mauna Kea 88-Inch Telescope for your use (DOH Facility ID# 9-603620). Petroleum was found in the confirmation samples at levels below the Tier 1 action levels. However, one sample of supplemental backfill material contained 2.07 mg/kg-of-benzo-a-pyrene. The DAGS consultant coordinated additional characterization of the backfill material with one of your RPMs (Mr. Shaobin Li). The additional samples contained levels of benzo-a-pyrene below the Tier 1 action levels. Therefore, the consultant recommended no additional follow-up at the site.

2000



Edward K. Noda and Associates, Inc. 615 Piikvi Street, Suite 300 Honolulu, Hawaii 96814-3116 Voice: (808) 591-8553 ext. 210

Fax: (808) 593-8551

Memorandum (C.N. 2170-02F)

March 5, 2002

To: DOH, Solid and Hazardous Waste Branch Attn: Shaobin Li 586-4226 fax: 586-7509

From: Charles Brown

Subject: Underground Storage Tank Closure

University of Hawaii 88" Telescope, Mauna Kea Summit

Facility ID No. 9-603620, Release ID No. 020006

### BACKGROUND:

During the removal and closure of the subject fuel storage tank, a soil sample was taken from the backfill material obtained from the area known as the Mauna Kea Quarry. This sample was collected immediately before placement of the backfill and analyzed for reporting purposes after the UST backfill was completed. Laboratory analysis of this sample indicated detectable levels of TPH as Diesel (TPH-D), Benzo(a)pyrene and Fluoranthene.

The detection of these substances indicates that a small diesel fuel spill may have occurred at the quarry site at some previous (unknown) date or contaminated material from the operation and/or construction of other observatories may have been placed at the quarry. Since there were no visual or odor indications of a spill, it is believed that any spill which may have occurred was less than the 25 gallon HEER reporting limit.

The analyte of concern in closing the UST is Benzo(a)pyrene. The backfill sample (217002-S3) indicated a Benzo(a)pyrene level of 2.07 ppm (see Table 5 attached). The Hawaii Department of Health (DOH) Tier 1 Action Level for Soil and Ground Water (ALSG) for Benzo(a)pyrene is 1.0 ppm. This level is the baseline DOH action level based on direct exposure and does not give consideration of the depth to ground water.

Additionally, there is an indication that the TPH-D, Benzo(a)pyrene and Fluoranthene contamination detected in the backfill is limited to a small portion of the material used. A post-work environmental soil sample was taken at the site. This sample (217002-BS2) consisted of a composite sample taken from five (5) areas over and downwind of the UST location. Two (2) aliquots of this sample were taken over the UST, and consisted of the backfill material. The results of this sample were "no detectable levels" of TPH-D, Benzo(a)pyrene or Fluoranthene. If the contamination in the backfill were evenly distributed, sample 217002-BS2 should have had a TPH-D level of 52 ppm, a Benzo(a)pyrene level of 0.8 ppm and a Fluoranthene level of 1.0 ppm.

p. 2

All parties involved assumed that the Mauna Kea quarry material was clean. The Office of Mauna Kea Management directed that any additional backfill material needed by the contractor must be native material. The location of the borrow site was designated by Mauna Kea Observatory Support Services. Approximately 20 cubic yards of material was excavated, hauled and placed on

December 3, 2001. This material extends down to a depth of 2.8 feet.

Due to frequent winter snow storms and high winds at the site, no additional site work is planned prior to June 2002. Between December 3, 2001 and June 2002, EKNA believes that significant attenuation of the limited amount of Benzo(a)pyrene in the backfill material may occur, especially considering that the site is 13,750 feet above Mean Sea Level. It is expected that the Benzo(a)pyrene level in June will be less than the Hawaii Department of Health's Action Levels for Soil and Ground Water (ALSG) Tier 1 Ilmit and the EPA Direct Contact limit of 1.0 ppm.

### PROPOSED ACTIONS:

EKNA proposes collecting two (2) grab samples from the 20 cubic yards of in-place backfill material from a depth of 1.5 to 2.5 feet for analysis of Benzo(a)pyrene. If the two (2) samples indicate that the June Benzo(a)pyrene level is less than 1.0 ppm, then EKNA will submit a closure report recommending no further action.

If the Benzo(a)pyrene level in the in-place backfill still exceeds the ALSG, EKNA will seek a source of clean native material to replace the in-place contaminated backfill.

### DOH CONCURRENCE:

EKNA requests the concurrence of DOH with this proposed sampling and analysis action for site closure.

Please call me at 591-8553 x 210 if you have any questions. Thank you for your assistance.

Sincerely,

Charles D. Bkown Charles G. Brown

**Environmental Physicist** 

Attachment: Current Sample Results



APR 2 9 2015

VIRGINIA PRESSLER, M.D.

STATE OF HAWAII DEPARTMENT OF HEALTH

P. O. BOX 3378 HONOLULU, HI 96801-3378

April 28, 2015

In reply, please refer to: File:

U0411RI

CERTIFIED MAIL NO. 7013 1710 0000 7659 9675 RETURN RECEIPT REQUESTED

Mr. Stewart Hunter, General Manager Mauna Kea Observatories Support Services 177 Makaala Street Hilo, Hawaii 96720

Dear Mr. Hunter:

SUBJECT:

Application for an Underground Storage Tank Permit

Mauna Kea Observatories Support Services

Hale Pohaku, HI Permit No. P-2015-045 Facility ID No. 9-600476

The Hawaii Department of Health (DOH), Underground Storage Tank (UST) Section has received and reviewed Mauna Kea Observatories Support Services' (MKOSS's) application for a UST permit dated January 13, 2015. The application requests that the DOH issue a permit to MKOSS to operate one (1) 12,000-gallon diesel, one (1) 2,000-gallon gasohol, and one (1) 4,000-gallon gasohol UST at MKOSS, Hale Pohaku, Hawaii. The DOH hereby approves the application. The enclosed permit (Permit No. P-2015-045) is issued under the provisions of Hawaii Revised Statutes, Chapter 342L, and Hawaii Administrative Rules, Title 11, Chapter 281, and is valid for five (5) years from the effective date.

Please review the permit carefully, and ensure that you, your employees, contractors, and consultants comply with all applicable Hawaii UST rules during the operation of the UST or tank systems at the facility.

Should you have any questions, please contact Ms. Roxanne Kwan of the Solid and Hazardous Waste Branch at (808) 586-4226.

Sincerely,

STUART YAMADA, P.E., CHIEF Environmental Management Division

Enclosures:

Permit No. P-2015-045

Receipt for filing fee

C:

Hawaii Fire Prevention Bureau (w/permit only)

Mr. Alika Toledo, Mauna Kea Observatories Support Services (w/enclosures)

www.carrollcox.com 808-782-6627



### STATE OF HAWAII DEPARTMENT OF HEALTH P.O. BOX 3378 HONOLULU, HAWAII 96801

DEC 20 2001

BRUCE S. ANDERSON, Ph.D., M.P.H.

In reply, please refer to: EMD/SHW

December 20, 2001

U12050SL

Mr. Ron Koehler General Manager Mauna Kea Observatories Support Services 177 Makaala Street Hilo, Hawaii 96720

Dear Mr. Koehler:

SUBJECT:

University of Hawaii 88 Telescope, Summit of Mauna Kea

Facility ID No. 9-603620/ Release ID No. 020006

This letter is in response to a telephone report dated November 19, 2001 from Mr. Charles Brown of Edward Ka Noda and Associates, regarding a release of petroleum product associated with a 4,000-gallon diesel underground storage tank (UST) located at the subject facility.

Hawaii Administrative Rules (HAR, Chapter 11-281) entitled "Underground Storage Tanks" require that UST owners and operators investigate and clean up releases of regulated substances from their UST systems. To assist you in complying with these requirements, the Department of Health has prepared a guidance document, entitled the *Technical Guidance Manual* (TGM) for Underground Storage Tank Closure and Release Response (March 2000). The guidance identifies the type and content of reports which should be submitted to our office after identification of a release. Enclosed is Section 5 of the TGM which addresses how to respond to a discovered release.

The reports which should be prepared and submitted to our office are:

- Confirmed Release Notification Form. Submit this form within 7 days of identifying the release. (HAR, 11-281-72)
- Current Evidence of Financial Responsibility. Submit current evidence of financial responsibility (for example, a copy of a current UST insurance policy) within 30 days of identifying the release. (HAR, 11-281-110)

- 3. **Initial Release Response Report.** Submit this report within 90 days of identifying the release. (HAR, 11-281-80.1)
- 4. Quarterly Release Response Report. If release response has not been completed within 90 days of identifying the release, submit this report within 180 days and every 90 days thereafter until release response actions have been completed. (HAR, 11-281-80.1)

Please initiate release response activities as soon as practicable. You should note that we typically do not require prior approval of plans for response activities at UST release sites; therefore, you may be relying heavily on the recommendations and work performed by your environmental consultant. Selection of a qualified consultant is of great importance. The consultant you select should be competent and capable of performing all necessary environmental services, and should provide you with all necessary reports and documentation to demonstrate compliance with the UST release response requirements as well as any other environmental laws applicable to the response activities at your facility.

We appreciate your cooperation and prompt attention to this matter, and look forward to receiving your report(s) on your release response actions. Please use the UST Facility ID number and Release ID number provided on the first page of this letter on all future correspondence with us regarding this release. Should you have any questions regarding this letter, please contact the Underground Storage Tank Section at (808) 586-4226.

Sincerely

SHAOBIN LI

Environmental Health Specialist Underground Storage Tank Section Solid and Hazardous Waste Branch

Enclosure

Able Pohuku

NEIL ABERCROMBIE GOVERNOR OF HAWAII



NOV 21 2014 F

LINDA ROSEN, M.D., M.P.H. DIRECTOR OF HEALTH

# STATE OF HAWAII DEPARTMENT OF HEALTH ENVIRONMENTAL MANAGEMENT DIVISION SOLID AND HAZARDOUS WASTE BRANCH

919 ALA MOANA BOULEVARD, #212 HONOLULU, HAWAII 96814 In reply, please refer to: EMD/SHWB

November 20, 2014

U1111RI

# CERTIFIED MAIL NO. 7013 1710 0000 7660 1026 RETURN RECEIPT REQUESTED

Mr. Stewart Hunter General Manager Mauna Kea Observatories Support Services 177 Maka'ala Street Hilo, Hawaii 96720

Dear Mr. Hunter:

SUBJECT:

Hale Pohaku Ranger Station

Mauna Kea Observatory Support Center, Hilo, HI

Facility ID No. 9-600476 Field Citation No. 3171

This is a follow-up to the November 6, 2014 inspection of the underground storage tank (UST) system located at the subject facility. The inspection was conducted by Mr. Roy Dennis Ilaga of the Department of Health (DOH), Underground Storage Tank Section. During the inspection, violations of the Hawaii Administrative Rules (HAR) UST regulations (Chapter 11-281) were noted for one (1) 12,000-gallon, one (1) 4,000-gallon, and one (1) 2,000-gallon USTs.

We are issuing a fine in the amount of \$1,800.00 and the enclosed "Field Citation/Settlement Agreement" (Field Citation). The following summarizes the violations that were found:

- HAR 11-281-51(c) Failure to properly service or maintain release detection equipment in the time frame specified.
   Fine: \$900.00
- HAR 11-281-53(1) Failure to conduct proper test of operability of line leak detector at least every 365 days.
   Fine: \$300.00

Mr. Stewart Hunter November 20, 2014 Page 2

HAR 11-281-53(1)(A) – Failure to conduct proper line tightness testing every 365 days on pressurized piping.
 Fine: \$600.00

Total penalty issued: \$1,800.00

Please read the Field Citation carefully. If you agree with the Field Citation, you have thirty (30) calendar days from the receipt of this letter to: 1) provide a description of all the actions taken to correct the violations; 2) sign the "Agreement by Owner or Operator" on the back of the Field Citation certifying that the violations have been corrected; and 3) mail a cashier's or personal check made out to "State of Hawaii." You have the option of not complying with the terms of the Field Citation. However, the DOH may proceed with standard enforcement actions, which could result in a higher penalty.

Should you have any questions, please contact Mr. Roy Dennis Ilaga of our Underground Storage Tank Section at (808) 586-4226.

Sincerely,

STEVEN Y.K CHANG, P.E., CHIEF Solid and Hazardous Waste Branch

Enclosure

### HAWAII DEPARTMENT OF HEALTH

Solid and Hazardous Waste Branch Underground Storage Tank Section 919 Ala Moana Blvd., Room 212 Honolulu, Hawaii 96814

### FIELD CITATION/SETTLEMENT AGREEMENT

NOTICE OF CITATION	this form. If the Settlement Agreement is no 30 calendar days of the date of inspection, th withdrawn, without prejudice to DOH's abilit		
On 1 106 1204, at 1:10 am/gm at the Facility known as:  HALE POWAKU RANGER STATION  located at:	actions for the above or any other violations.  I have personally observed the violations descand operator in violation of the above-referen		
Mauria Kra Oles. Support Center Hito H 96720	(Signature of DOH Inspector)		
1D number: 9-600476	RECEIPT BY OWNER OF		
in the presence of the Owner/Operator/On-site Representative:	I hereby acknowledge receipt of this Notice of		
an authorized employee of the Hawaii Department of Health (DOH) inspected this facility to determine compliance with underground storage tank regulations promulgated under chapter 342L, Hawaii Revised Statutes (HRS).	(Signature of Owner, Operator or On-site Rep. sent by certified mail no. 7013 (Print Name)		
This inspection revealed the following violations:			
*§ 11-281-51(C), HAR Settlement: \$ 900	(Print Title)		
Violation. Failure to properly service or maintain release	(Print Mailing Address of Owner or Operator)		
detection equipment in the time frame specified (3 tonle	3		
Date(s): 3  3  3 - 4 9  70 4	INSTRUCTION		
*\$ 11-281-53(1) , HAR Settlement: \$ 300  Violation: Failure to conduct proper test of operability of line leak detector at least away 365 days.  Date(s): 7/17/13 - 4/9/2014 (2 ALLDS)  *\$ 11-281-53(1)(A) , HAR Settlement: \$ 600  Violation: Failure to anduct proper line tight runs testing every 365 days on preynolized pring Date(s): 7/17/13 - 4/9/2014 (2 preynolized pring)  *\$ 11-281, HAR Settlement: \$	If you wish to avoid enforcement actions and p noted of up to \$25,000 per tank per day for ear participate in an expedited settlement by:  1. Correcting all of the violations noted by the 2. Providing a description of all of the actions violations in the blank space provided below, a information that does not fit within the space prof any records or other documents evidencing to the violations;  3. Signing the Settlement Agreement and Cert after you have corrected all of the violations;  4. Submitting a cashier's or personal check may for the full payment of the "Proposed Settlement of Citation section, together with the original of the top left of this form  WITHIN THIRTY CALENDAR DAYS  DATE.		
Violation:	DESCRIPTION OF CORR		
	in the space below, please describe the work per violations, attaching additional pages if you need of all documents describing the work that was pe		
*HAR means the Hawaii Administrative Rules			
Proposed Settlement Total:			

FIELD CITATION No:

### FIELD CITATION ORDER

The owner and operator are hereby ordered to correct the violations described in the Notice of Citation section of this form.

The Field Citation Order is not an adjudicatory proceeding or contested case under chapter 91. HRS but is an offer to settle an administrative case that is issued solely with reference to the Settlement Agreement on the reverse of t returned in correct form within is Field Citation Order is hereby ty to file additional enforcement

I have personally observed the v	violations described above, and	find the	OWEAR
and operator in violation of the	above-referenced regulations.	tind the	OWINCI

### ROPERATOR

Citation/Field Citation Order

Date: resentative)

1710 0000 7660 1026

enalties for the violations ch violation, you may

- inspector;
- you took to correct the ttaching additional pages for rovided, and attaching copies he actions you took to correct
- ification on the reverse side
- ade out to "State of Hawaii" nt Total" noted in the Notice this form to the address at

OF THE INSPECTION


### ECTIONS

rformed to correct the d more space. Attach copies erformed.

(SFC Form 5/00)

Original: white / File Copy: yellow







LAWRENCE MIIKE

SEP - 9 1997 ·

DIRECTOR OF HEALTH

### STATE OF HAWAII

DEPARTMENT OF HEALTH P.O. BOX 3378 HONOLULU, HAWAII 96801

In reply, please refer to: EMD/SHW

September 3, 1997

U0980RT

Mr. Ron Kohler Mauna Kea Support Services 177 Makaala Street Hilo, Hawaii 96720

Dear Mr. Kohler:

Subject:

Hale Pohaku Mid-Level Facility

Facility ID 9-600476

Thank you for your return of the "Verification of Compliance" form regarding the Underground Storage Tank (UST) inspection conducted by Mr. Richard Takaba on February 27, 1997 at the subject facility.

We urge you to continue your compliance with the U.S. Environmental Protection Agency's (EPA) technical standards and financial responsibility as described in Title 40 of the Code of Federal Regulations, Part 280 (40 CFR Part 280).

As a reminder, on December 22, 1998, all owners and operators of UST systems must have spill and overfill prevention equipment and corrosion protection for USTs and piping as described in 40 CFR Part 280, Subpart B. The EPA will not extend this deadline.

If you have any questions concerning the inspection or the federal UST regulations, please contact Mr. Takaba at (808) 586-4226.

Sincerely,

CHANG, P.E.

Solid and Hazardous Waste Branch

SYKC:RT:Ino



MAR 25 1997

LAWRENCE MIIKE DIRECTOR OF HEALTH

STATE OF HAWAII
DEPARTMENT OF HEALTH
ENVIRONMENTAL MANAGEMENT DIVISION
SOLID AND HAZARDOUS WASTE BRANCH

919 ALA MOANA BLVD., #212 HONOLULU, HAWAII 96814

March 20, 1997

In reply, please refer to: EMD/SHW

U0351RT

### WARNING LETTER

Mr. Ron Koehler Mauna Kea Observatories Support Services 177 Makaala Street Hilo, Hawaii 96720

Dear Mr. Koehler:

Subject:

Hale Pohaku Mid-Level Facility

Facility I.D. 9-600476

Thank you for your cooperation with Mr. Richard Takaba of our Underground Storage Tank Section during his February 27, 1997, inspection of the underground storage tank (UST) system. The inspection was conducted under the authority of Section 342L-7 of the Hawaii Revised Statutes.

During the inspection, the following violations of the U.S. Environmental Protection Agency's (EPA's) and UST regulations (40 CFR Part 280) were noted:

### Inventory Control

- A monthly reconciliation of inventory control records for UST 1 (12,000 gallon diesel), UST 2 (2,000 gallon regular gasoline) and UST 3 (4,000 gallon regular gasoline) was not performed such that a release greater than 1.0 percent of flow-through plus 130 gallons could be detected during any given month as required by 40 CFR 280.43(a);
- Inventory volume measurements for regulated substance inputs, withdrawals, and the amount still remaining in the tank were not recorded for UST 1 (12,000 gallon diesel), UST 2 (2,000 gallon regular

gasoline), and UST 3 (4,000 gallon regular gasoline) each operating day as required for inventory control by 40 CFR 280.43(a)(1);

- Regulated substance inputs into UST 1 (12,000 gallon diesel), UST 2 (2,000 gallon regular gasoline) and UST 3 (4,000 gallon regular gasoline) were not reconciled with delivery receipts by measurement of the tank inventory volume before and after delivery as required for inventory control by 40 CFR 280.43(a)(3);
- Product dispensing from UST 1 (12,000 gallon diesel), UST 2 (2,000 gallon regular gasoline) and UST 3 (4,000 gallon regular gasoline) was not metered and recorded within the local standards for meter calibration as required for inventory control by 40 CFR 280.43(a)(5);
- Inventory control records for UST 1 (12,000 gallon diesel), UST 2 (2,000 gallon regular gasoline) and UST 3 (4,000 gallon regular gasoline) did not include monthly water monitoring to the nearest one eighth of an inch as required by 40 CFR 280.43(a)(6);
- Inventory control records for UST 1 (12,000 gallon diesel), UST 2 (2,000 gallon regular gasoline), and UST 3 (4,000 gallon regular gasoline) were not maintained for at least one year as required by 40 CFR 280.45(b);

### Tank Tightness Testing

- Tank tightness testing conducted for UST 1 (12,000 gallon diesel),
   UST 2 (2,000 gallon regular gasoline), and UST 3 (4,000 gallon regular gasoline) was not used in conjunction with inventory control and was not conducted every year as required by 40 CFR 280.41(a)(2);
- Written performance claims pertaining to the tank tightness testing system used to detect releases from UST 1 (12,000 gallon diesel), UST 2 (2,000 gallon regular gasoline), and UST 3 (4,000 gallon regular gasoline), and the manner in which these claims have been justified or tested (e.g., a third-party certification), were not maintained for five years as required by 40 CFR 280.45(a);
- Tank tightness testing records for UST 1 (12,000 gallon diesel), UST 2 (2,000 gallon regular gasoline), and UST 3 (4,000 gallon regular gasoline) were not retained until the next test was conducted as required by 40 CFR 280.45(b);

Mr. Ron Koehler March 20, 1997 Page 3

### Automatic Line Leak Detector

- Documentation was not available for UST 1 (12,000 gallon diesel), UST 2 (2,000 gallon regular gasoline), and UST 3 (4,000 gallon regular gasoline) demonstrating that an annual test of the operation of the automatic line leak detectors was conducted as required by 40 CFR 280.45(c) and 280.44(a);
- Written documentation of all calibration, maintenance, and repair of the automatic line leak detectors for UST 1 (12,000 gallon diesel), UST 2 (2,000 gallon regular gasoline), and UST 3 (4,000 gallon regular gasoline) was not maintained for at least one year as required by 40 CFR 280.45(c);

### Line Tightness Testing

- Line tightness testing was not conducted for UST 1 (12,000 gallon diesel), UST 2 (2,000 gallon regular gasoline), and UST 3 (4,000 gallon regular gasoline) every year as required by 40 CFR 280.41(b)(1)(ii);
- Written performance claims pertaining to the line tightness testing system used to detect releases from UST 1 (12,000 gallon diesel), UST 2 (2,000 gallon regular gasoline), and UST 3 (4,000 gallon regular gasoline), and the manner in which these claims have been justified or tested (e.g., a third-party certification), were not maintained for five years as required by 40 CFR 280.45(a);
- Line tightness testing records for UST 1 (12,000 gallon diesel), UST 2 (2,000 gallon regular gasoline), and UST 3 (4,000 gallon regular gasoline) were not maintained for at least one year as required by 40 CFR 280.45(b).

Please correct the above-mentioned violations and return the enclosed "Verification of Compliance Status" form to the Department of Health (DOH) within forty five (45) days of the date of this letter. Under the authority of Section 9006 of the Resource Conservation and Recovery Act, EPA has the authority to issue penalties up to \$10,000 for each tank for each day of violation. Such penalties are not being levied at this time. However, DOH retains the right to refer this facility to EPA to impose such penalties if the violations are not corrected within the time specified.

Mr. Ron Koehler March 20, 1997 Page 4

During the inspection, it was noted that your UST system does not have spill prevention equipment, overfill prevention or corrosion protection for the piping. This is a reminder that all UST systems must comply with the requirements specified in 40 CFR Part 280.20 by December 22, 1998. Also, as your corrosion-resistant tanks were installed in 1983, you have 10 years to continue using inventory control with periodic tank tightness testing or until December 22, 1998, whichever is later in accordance with 40 CFR Part 280.41(a). After this time, tanks must be monitored at least every 30 days for releases using one of the methods listed in 280.43 (d) through (h) in accordance with 280.41(a).

If you have any questions concerning the violations or the steps required to bring the facility into compliance with the federal UST regulations, please contact Mr. Takaba at 586-4226.

Sincerely,

STEVEN Y.K. CHANG, P.E. CHIEF
Solid and Hazardous Waste Branch

SYKC:RT:sc

Enclosure

c: Norwood Scott, EPA Region IX, San Francisco Bob McLaren, UH Institute for Astronomy, Honolulu

# Hawai. DOH UST Inspection Check..st 9-600476

1. Owner  Mauna Kea 06s. Suppot Services  owner name 177 Ma Kaala St.  street address Hilo 96720  city state zip code  contact person at main office phone #					Serviè 6. 6720 zip code	(e)	fac stre	II. Location  Hale Pahake Mid-level facility name & identification number  street address  city Ron Kochler 93 71605  contact person at location phone #		
	TANK	PIPING	TANK 2	PIPING	TANK	PIPING	TANK	PIPING		
III.									tank identification number (copy page if necessary) currently in use temporarily out of use permanently out of use	
IV. V.	12,00	b	2,000		4,000				installed before December 22, 1988 installed on or after December 22, 1988	
v. VI.				Y	<u> </u>	V			capacity in gallons single wall steel	
									double wall steel jacketed or clad steel single wall fiberglass reinforced plastic double wall fiberglass reinforced plastic other:	
VII.			-		-				suction piping pressurized piping	
VIII.					<b>b</b>				gasoline diesel gasohol heating oil used oil other:	
IX.									manual tank gauging tightness testing inventory control	
									automatic tank gauging ground water monitoring vapor monitoring interstitial monitoring statistical inventory reconciliation automatic line leak detector	
х.						<u>.</u>			other:	
		-		Cara		[call	Pan -	<b>&gt;</b>	spill prevention (if installed on or after 12/22/88) overfill prevention (if installed on or after 12/22/88) corrosion protection (if installed on or after 12/22/88) financial responsibility  The Ast	
P	shoul		Kaba	_ certify th			e above nam	ned facility	956-8768	
inspecto	(print name) (date & time) spector's signature: 120027441							- 1	(date & time)	

Inve	ntory Control elt-z	
UST:	123	
alt-a		monthly reconciliation performed (1% through put + 130) 280.43(a) method expiration date has not yet passed:
elt-b		December 22, 1998, or 10 years after installation, or 10 years after upgrading existing tank, whichever is later
alt-c		daily tank liquid level measurements
alt-d	444	1/4th inch accuracy in tank liquid level measurements 280.43(a)(2)
alt-e		before/after delivery tank liquid level measurements reconciled with volume according to delivery receipt 280.43(a)(3)
alt-f	9990	drop tube present in tank fill pipe
ait-g		dispenser meter calibrated
alt-h		monthly check for water
olt-i	XXX	inventory records on file for one year
ter-William .		
Stati	stical Inventory R	econciliation (SIR) alt-z.
UST:		NEED MONTHLY CHECK FOR WATER
elt-j elt-k elt-m		inventory conducted according to provider's specifications 280.40(a)(2) statistical analysis is performed every month 280.41(a) certification of performance on file
alt-i		statistical analysis results on file for one year

<b>√</b>	= -	in compliance did not verify	facility identification number:	9-600476
х	=	not in compliance	inspector's initials:	Nt.
n	=	not applicable	date:	1/27/97

Tank	Tightness	Testing	alt-z

UST:	123_	
alt-s		system is (if appl.): installed, calibrated, operated, and maintained according to manufacturer's instructions 280.40(a)(2)
alt-t		performance requirements: method was installed before December 22, 1990 or able to detect a .1 gph leak with a .95 PD and .05 PF 280.40(a)(3) tank tightness test conducted:
alt-u		<ul> <li>a. in conjunction with manual tank gauging (tanks with 2,000-gallon nominal capacity or less only) or in conjunction with inventory control</li> </ul>
		b. every five years (corrosion protected tanks with spill and overfill protection only) or every year
alt-m		certification of performance on file for five years . 280.45(a) & 280.40(a)(3)
alt-i	口对改改	results of last test on file
alt-v		if test device permanently installed, records of calibration, maintenance, and repair for last year

in compliance did not verify not in compliance not applicable

facility identification number:  $7-600^{\circ}$  inspector's initials: 2/21/91

Pipir	g (pressurized)	ak detector alt-z
1.	automatic line lea	ık detector at-z
UST: alt-s alt-t ctr-v alt-m alt-j alt-v		detector is:     installed,     calibrated,     operated, and     maintained according to manufacturer's instructions
alt-v		calibration, maintenance, and repair records on the for one year. 200.40(c)
UST: alt-s alt-t ctr-s alt-m alt-i	1 2 2	tightness test is (if appl.):     installed,     calibrated,     operated, and     maintained according to manufacturer's instructions 280.40(a)(2)  performance requirements:     method was installed before December 22, 1990 or     able to detect a .1 gph leak at 1½ times operating     pressure with.95 PD and .05 PF
alt-v		if permanently installed
		OR
ctr-t		monthly method (specify): 280.44(c)
✓ □ x	= in compl = did not v = not in co	rerify facility identification number: 7-600976 empliance inspector's initials:

# UST - GPS Data Collection

Facility ID	9-600476					
Facility Name	Hale Pohaku Mid-Level Facility					
Street	Maura Kea Observatory Access Rd.					
City	ltilo zip					

Tank #	Date	Time	File Name	Bearing	Initials
2	2/27/97	1049	F022720A	un konsun	RA
					2-
		KO.			

Notes:


alighment of tanks unknown.

## HAVAII DEPARTMENT OF HEALTH UST OPERATIONAL INSPECTION CHECKLIST

9-600476

Owner of tank(s)  State d'Hausi V.H. Mauraha supart serva owner's name			-			
117 Makaala 84 mailing address				Many Kin access Read Man Relate Racogo H. Services pocasion address (P.O. Box not acceptable)		
Hilo	(+/)	46710 zip code	ō	tilo HI 96270 ty state zip code		
808974 4705	80093			Ren kethin 8089394203		
Ren Keehler	fax#		c	ontact person at location phone #		
contact person's name	fax#		(	perator of tank(s)		
Comments:			ō	perator's name		
			m	ailing address		
			ci	state zip code		
			pl	ione# fax#		
TANK	TANK	TANK	TANK			
	- glas-			TANK IDENTIFICATION NUMBER (use additional pages if necessary)		
				STATUS OF TANK(S)		
11,000	4000	1000		capacity in gallons		
1/83	8/63	8/63		date of installation (permit #)		
		9		currently in use		
All research the distribution of the second second			***************************************	if temporarily closed, give date		
				if permanently closed, give date		
			□·	tank connected to an emergency generator		
				SUBSTANCE CURRENTLY OR LAST STORED		
	0_			gasoline, specify grade		
0				diesel		
				used oil		
	H			heating oil		
				gasohol other:		
nspector: STE (-4	N BORNET	_ Inspector's signatu	ne. Alda	n Doloh date: 4/80/04 time: 8:30		
Received by: RO		LE/CReceived by		The state of the s		
				d as a coutesy. It does not limit the inspector's ability		
o cite the facility at a	a later date for	additional violations.	13 provide			
				page 1 of		

White - Original Yellow - File Copy



# tanks installed before December 22, 1988.

spill and overfill prevention devices. tank system (UST) must have corrosion protection and Upgrading simply means that your underground storage

possible to help avoid the cost of cleaning up leaks from substandard USTs. Although the federal regulatory deadline for compliance is 1998, you should make these improvements as soon as

# For More Information

substandard UST. ask questions about what it takes to upgrade a You can call EPA's toll-free Hotline at 800-424-9346 to